

No. HQ-OPBD0BD(STNT)/7/2020 (6902)

Date : 19.12.2022

**DFCR, Business Development Circular No. 12 of 2022  
(DFCR/BD - 12/2022)**

**Sub : Maintenance of separate priority between BOBYN and other rakes to be supplied at New Dabala Station**

\*\*\*\*\*


The loading of BOXN and BOBYN rakes at New Dabala Station over WDFC is being done on single indent priority in which BOXN rakes are loaded from Line No. 1A and BOBYN rakes are loaded from Line No. 1.

In view of operational facilities at New Dabala Station, simultaneous loading is not feasible in line number 1 & 1A. In order to improve freight loading, the Competent authority has decided that a separate priority will be maintained at New Dabala Station for indents placed for BOBYN rakes and for other rakes. Accordingly the following procedure should be followed for booking and supply of rakes at New Dabala station:

1. Indent placed for BOBYN rakes should be separate from other general indents as BOBYN rakes move in close circuit between DFCCIL-NR after unloading returned to DFC for next loading.
2. BOBYN rakes supplied in lieu of the separate indent priority should be loaded from line No. 1
3. BOXN and other rakes supplied under the general indent should be placed at line No. 1A.

JGM/OP&BD/WDFC may advise the concerned to follow the above procedure for booking and loading over New Dabala Station.

This issued with the approval of Competent Authority.

  
19/12/22

**(Shobhit Bhatnagar)  
GGM/OP&BD-I**

Copy to :

1. DIR.OP&BD for Kind information please.
2. All CGMs and GGMs/DFCR
3. GGM/OP&BD-II, GM(OP), GM(TS), AGM/BD, CVO, AGM/TS, and JGM/OP&BD/WDFC