

## डेडीकेटेड फ्रेंट कोरीडोर कॉर्पोरेशन ऑफ इंडिया लि. भारत सरकार (रेल मंत्रालय) का उपक्रम Dedicated Freight Corridor Corporation of India Ltd.

A Govt. of India (Ministry of Railway) Enterprise

MUMBAI NORTH No:-MUM/N/RTI/ 407-I

Date 06/05/2025

JGM/ADMIN(CPIO)
DFCCIL, New Delhi

Sub: - Providing of Information under the provision of the RTI Act 2005. Case of Shri Manish V Patel Mograwadi Near Railway Station Valsad Near Ramesh Guest House Mograwadi - RTI -288

Ref: - Westren Railway- Mumbai Divison on 22/04/2025 with reference number WRLMD/R/T/25/00242.

Vide above referred letters, the applicant has sought the information as stated in column 1. (attached). The reply to be given regarding the information sought is being attached.

Encl. 1.Reply duly approved by CGM/N/MUMBAI 2. Original Application seeking information

(Bratati Banerjee)
APM/HR
Mumbai, (North) DFCCIL

Mumbai, (North) DECCIL

## Note

Sub:-RTI of Shri Manish V Patel Mograwadi Near Railway station valsad Near Ramesh Guest House Mograwadi -RTI-288

Ref:- Western Railway -Mumbai Division on 22/04/2025 with reference number: WRLMD/R/T/25/00242.

The detailed remarks are tabulated below: -

Sl No	Query in RTI	Reply
1	Was any No Objection Certificate (NOC) or permission obtained from residents before DFCCIL Constructed freight tracks within 30 metres of houses in my area? If yes, Provide copies.	As per Railway circularNo.W419.L.NOC(GEN)III 28.05.2014 minimum clearance of 3.00m between Railway boundary and nearest edge of building shall be ensured. In case of Shri Manish V Patel Mograwadi Near Railway station valsad Near Ramesh Guest House Mograwadi, his house is at a distance of 12.55 m from DFC UP line and concrete boundary wall has been constructed at Railway/DFC boundary to ensure safety.  As new house has not been constructed with in 30m of railway boundary by the resident and the house exists before laying DFC track, NOC is not required.
2	Provide a copy of project plan and alignment approval for DFCCIL track laid 12.55 meters from my residence.	The available project plan and alignment can be collected from DFCCIL office, ENGINEERS BUILDING, 1st Floor, Pramuk darshan 4,near Dmart, valsad to Atul road ,pin 396007-Valsad, Gujarat.
3	Share copies of any internal or third- party safety inspection or vibration impact reports conducted before or after construction of the said track.	A safety inspection was conducted by DFC officials Executive Engg/BL and Jr.Executive Engg/BL on 07.04.2025. The inspection report is enclosed here with.
4	Was any structural or environmental impact assessment done prior to construction near my house? If yes, provide full details.	All necessary statutory guidelines have been followed before construction and laying of DFCCIL track.
5	Provide names and designation of official involved in planning and executing DFCCIL track project in my area.	The planning and execution of DFCCIL track done after approval of same from competent Authority of DFCCIL/Railways.



6	Provide compensation policy applicable to residents whose properties suffered damage due to freight train operations. Was my property assessed for this? If yes, Share inspection or rejection reports.	Compensation shall be paid as per Land acquisition act of Railway to the land losers and PAPs.  As the house of Shri Manish V Patel is at a distance of 12.55m from DFC UP track and no damage has been occurred due to movement of train on DFC track, compensation of the house is not permitted. As DFC has laid track on DFC/Railway land, no compensation is allowed.  A safety inspection was conducted by DFC officials Executive Engg/BL and Jr.Executive Engg/BL on 07.04.2025 and confirmed that, the house of Shri Manish V Patel is at a distance of 12.55 m from DFC UP line track and no vibration observed at this house due to train movement and no structural damage has occurred in this house due to train movement. The inspection report is enclosed here with.
7	Was any public consultation or hearing with affected residents conducted? If yes, provide notice copies and minutes	This information is not available in this office. All necessary statutory guidelines have been followed before construction and laying of DFCCIL track.
	of meetings.	f st : Marieb V Datel wore
8	Why is my grievance continuously being transferred to DFCCIL despite it clearly being a case of safety rule violation and potential structural damage?	Railway.
9	Since DFCCIL is under the ministry of Railways, what action has Western Railway taken against illegal construction of track so close to residentials areas, and what authority allowed such development?	resident area. All the work has been carried out on DFCCIL/Railway land. All necessary approvals have been taken from competent authority of DFCCIL/Railway for construction of DFCCIL track.
10	What steps are being taken by Western Railway to ensure DFCCIL Complies with Railway Board norms across India?	

Dy.PM/Engg/BL given by Executive Engg/B4/1 in above table.

Dj. CPM/Engg/BL is requested to forceard for

Dy.CPM/Engg/BL further approval of competent Authority.

APTO/Mim (M) 156/1.

Can (murpal) ColoTrorge

AM HREAPDOLMUM

	RTI REQUEST DETAIL	22/04/2025
Registration No.: D	FCCL/R/X/25/00004	Date of Receipt: 22/04/2025
V	Vestern Railway- Mumbai Division of	22/04/2025 With Reference Number:
	May kindly furnish the information	on, related to your office, within the ation is also transferred to CPIO-Division of WR and CPIO-DFCCIL
	Electronically Transferred from Other Public Authority	Request:
	A ANGLE VILLA VIRHAL PATEL	Gender: Male
Address:	Mograwadi Near Railway station, va	lsad Near Ramesh Guest House,
	Pin:396001 Gujarat	Country: Details not provided
	+91-6353956749	Mobile No.: +91- 6353956749
	xlines004manish@gmail.com Urban	Education Above Graduate Status:
Status(Rural/Urban):	Descile not provided	Letter Date: Details not provided
Letter No.  Is Requester Belov		Citizenship Indian Status
Poverty Line?		Mode of Payment
Amount Paid	0 (RTI fee is received by Western Railway (original recipient))	Payment Gateway
Does it concern the lit or Liberty of a Person?		Request Pertains to:
	The section not nertain to the oper	line Engineering Department.
Original RTI Tex	IRTI Text: As per the Right to Information Act 2005, I seek the following information regarding DFCCIL operations near my house:  Was any No Objection Certificate (NOC) or permission obtained from residents before DFCCIL constructed freight tracks within 30 meters of houses in my area? If yes, provide copies.  Provide a copy of project plan and alignment approval for DFCCIL track 12.55 meters from my residence.  Share copies of any internal or third-party safety inspection or vibration impact reports conducted before or after construction of the said track.  Was any structural or environmental impact assessment done prior to construction near my house? If yes, provide full details.  Provide names and designations of officials involved in planning and executing DFCCIL track project in my area.	

Provide compensation policy applicable to residents whose properties suffered damage due to freight train operations. Was my property assessed for this? If yes, share inspection or rejection reports.

Was any public consultation or hearing with affected residents conducted? If yes, provide notice copies and minutes of meetings.

Why is my grievance continuously being transferred to DFCCIL despite it clearly being a case of safety rule violation and potential structural damage?

Since DFCCIL is under the Ministry of Railways, what action has Western Railway taken against illegal construction of track so close to residential areas, and what authority allowed such development?

What steps are being taken by Western Railway to ensure DFCCIL complies with Railway Board norms across India?

I declare that I am an affected citizen and this information is requested in public and personal interest. Kindly send the reply within 30 days as per RTI Act 2005.

Print Save Close

# Details for registration number: MORLY/E/2025/0007493

Name Of Complainant

Manish V Patel

**Date of Receipt** 

07/03/2025

Received By

Railways, (Railway Board)

Ministry/Department

Grievance Description

Railways, ( Railway Board) >> Miscellaneous

Railway Board/ Zone/ PSU/ PU/ Office : Western Railway - Mumbai

I am filing this grievance regarding the critical safety hazard posed by the DFCCIL freight train track, which is only 3 meters away from my legally registered house. As per Railway Board guidelines, a minimum 30-meter distance is required between railway tracks and residential areas, yet this rule has been violated. No No-Objection Certificate (NOC) was been and so safety reasoned have been implemented issued, and no safety measures have been implemented.

Due to continuous train movement and vibrations, my house and surrounding residential area have suffered severe structural damage, making it unsafe for habitation. Despite multiple complaints to DFCCIL officials and the local surviving and consecution and continuous train movement and vibration. municipal corporation, no survey has been conducted, and no corrective action has been taken. Instead, authorities brought police forces to intimidate us, violating our rights and worsening our distress.

Immediate safety inspection of the area to assess the risk to residents.

Written clarification regarding the legality of residential proximity to the tracks. Full compensation for my damaged house and residential area due to DFCCIL's project and train operations.

If this issue is not addressed within 30 days, I will escalate it to the Railway Ministry, NHRC, and the High Court for legal intervention. I urge you to take urgent action to prevent further damage and ensure our safety.

Current Status	Under process	
Date of Action	10/03/2025	
	Officer Concerns To	
Officer Name	PG OFFICER (GENERAL MANAGER)	
Organisation name	DFCCIL STATION BUILDING	DG COMPLEX,NEW DELHI-110001
Contact Address	DECCIL 5TH FLOOR, SUPREME COURT METRO STATION BUL	
Email Address	anilkumar1965@dfcc.co.in	TO THE REAL PROPERTY.
Contact Number	01123454990	

# Reminder(s) / Clarification(s)

Reminder Date	Remarks
23/03/2025	Dear Sir/Madam,  This is a serious reminder regarding my grievance about the DFCCIL freight train track being only 3 meters away from my legally registered house. If immediate action is not taken, there only 3 meters away from my legally registered house. If immediate action is not taken, there only a meters away from my legally registered house. If immediate action is not taken, there only a meters of lives, including mine and is a high risk of a train accident that could result in the loss of lives, including mine and those of my fellow residents.  The continuous train movement and vibrations have already caused severe structural damage to our homes, making the area unsafe for habitation. Any further negligence could lead to a our homes, making the area unsafe for habitation. Any further negligence could lead to a tragic disaster. I urge you to treat this as a matter of utmost urgency and take the necessar tragic disaster. I urge you to treat this as a matter of utmost urgency and take the necessar steps without further delay.  Please act immediately to prevent a potential catastrophe. I look forward to your prompt response and action.

05/04/2025

This is my final and most urgent reminder regarding the extremely reckless and dangerous placement of the DFCCIL freight train track — a mere 3 meters from my legally registered residence. My previous complaint dated 23-03-2025 has been completely ignored, and this silence from your side amounts to gross negligence and willful disregard for human life.

The continuous vibrations from the freight trains are causing accelerated structural damage to our homes. Cracks are spreading, walls are shaking, and foundations are weakening. The entire locality is under physical and psychological stress. You are putting lives at immediate risk, including children, elderly, and working individuals who live here with the assumption that the government would protect, not endanger them.

Let me be absolutely direct: if any accident, injury, or death occurs due to this outrageous placement of the freight line, the blame will fall squarely on your department. There will be no excuse, and no protection from legal and public consequences. Every official who failed to act will be held personally accountable. This is not just an administrative lapse — it is a potentially criminal act of endangerment.

We are not going to wait quietly for disaster to strike. If this issue is not addressed immediately and decisively, I will escalate this matter through legal action, national media, human rights commissions, and public protests. You have been warned — this situation has crossed every line of acceptable delay and ignorance.

This is a matter of life and death. Take action now — or be prepared to face the full force of legal, civic, and public outrage.

## WESTERN RAILWAY

40 ex1486

RECEIVED

जनसूचनाअधिकारी मंडलरेलप्रबंधककाकार्यालय मंबईसेंटल,मंबई seniordennbct@gmail.com

Public Information Officer Office of Divisional Railway Manager ımbai Central, Mumbai -400008.

Tel: 02267644401

NEE IN THE ST SPINSONER IN THE PARTY File No: Engg/RTIA/ 237/24-25

dated\_0.02.2025

To.

Dr. Rolway Manager's Office I R & D D. S. M. Shri Manish V.Patel. Mogarwadi near Railway starion.

Valsad near Ramesh Guest House

Subject: - Supply of information under MINAL SUBJECT RAIL RTI Application by SHAND SHAND THE STREET STREET

Reference:-Registration Number WRLMD/R/E/25/00058 DTD 25/01/2025.

With reference to the above subject, it is to inform you that Engineering remarks are as under.

- 1. Minimum Distance Standards
- a) As per Railway Board guidelines the minimum distance required between main railway tracks and residential area is more than 30 meters. If it is less than 30 meters than Railway NOC is required.
- b) This guidelines is applicable all across the Indian Railways.
- c) Copy of the Railway Board Circular No. 2015/LML-I/19/2 DTD 25/06/2015 is enclosed herewith
- 2. Implementation in specific area zone.

a,b&c) No survey has been carried out on the East side of Mograwadi area to find out the actual distance between main railway tracks and the nearest residential area.

If not satisfied with the reply you can approach Appellant authority & Additional Divisional Railway ManagerADRM (OP&HR) Western Railway Mumbai central 400008 Phone po 67644544 & emailadrmnsmctwr@gmail.com within 30 days.

> Vijendra Kumar Meena Public Information officen & 25 Sr.Divisional Engineer (N)

Office of Divisional Railway Manager, Engg. Deptt. Mumbai Central.

Mumbai: 400008



## डेडीकेटंड फ्रंट काराडार कापारया जान र भारत सरकार (रेल मंत्रालय) का उपक्रम Dedicated Freight Corridor Corporation of India Ltd. A Govt. of India (Ministry of Railway) Enterprise

MUM/EN/N/CA-iii/367-V

Date: 12.04.2025

To. GM/LA & SEMU DECCIL

Sub: - Reply to the representation of Shri. Manish Patel.

Ref: - CPGRAMS No. MORLY/E/2025/0007493

With reference to the representation as received from Shri. Manish Patel R/o Mograwadi, Valsad, through CPGRAMS as reply is as enclosed herewith

Shekhar Vasant Deshpande)
Project Manager

(North) Mumbai, DFCCIL

C/- CGM/N

#### Note

Sub:-Grievances of Shri Manish V Patel Mograwadi Near Railway station valsad Near Ramesh Guest House Mograwadi, -registration number: MORLY/E/2025/0007493

Ref:- Grievances of Shri Manish V Patel registration number: MORLY/E/2025/0007493 dated

With reference to above, I, Executive/Engg/BL along with Jr. Executive Engg/BL have visited the house of Shri Manish V Patel Mograwadi Near Railway station valsad Near Ramesh Guest House Mograwadi. Following observations has been made in this regards:-

1. House has been inspected and following dimensions has been noted:-

ouse na	s been inspected and following dimensions has	Distance
SI No	Item	10.9m
1	Distance of Boundary wall of house from	
	DFC UP track	12.55m
2	Distance of Edge of house from DFC UP	
	track from	5.90 m
3	Distance of Boundary wall of house from	
	DFC/Railway boundary	7.55 m
4	Distance of Edge of house from DFC/Rallway boundary  of 12.55 m from DFC UP to	

The house is at distance of 12.55 m from DFC UP track and 7.55m from DFC/Railway

- 2. This house was inspected by DFC officials Executive Engg/BL and Jr. Executive Engg/BL and confirmed that no vibration observed at this house due to train movement and no such structural damage has occurred in this house due to train movement.
- 3. In this location concrete Boundary wall has been constructed at Railway/DFC boundary by DFCCIL to ensure safety. As new house has not been constructed with in 30m of railway boundary and the house exists before laying DFC track, NOC not required.
- 4. Immediate safety inspection carried out by DFC officials i.e Executive Engg/BL and
- 5. As the house is at a distance of 12.5m from DFC UP track and no damage has been occurred due to movement of train on DFC track, compensation of the house is not permitted on safety ground.
- 6. As DFC has laid track on DFC/Railway land, no compensation is permitted .

The detailed remarks of the grievances of Shri Manish V Patel Is tabulated below:-

			Reply	
No	Item	the state of the s	An inspection was carried out by Executive	
	safet track regis guid requ	In filing this grievance regarding the critical ty hazard posed by the DFCCIL freight train it, which is only 3 meters away from my legally listered house. As per Railway Board delines, a minimum 30-meter distance is quired between railway tracks and residential has, yet this rule has been violated. No Nonjection Certificate (NOC) was issued, and no fety measures have been implemented.	location and it was found that the house is a distance of 12.55 m from DFC UP line and 7.55 m distance from Railway Boundary. In the letter, the PAP has mentioned that the DFCCIL freight train is only 3 m away from his legally registered house is factually incorrect.  As per Railway circularNo.W419.LNOC(GEN)III 28.05.2014 minimum clearance of 3.00m between Railway boundary and nearest edge of building shall be ensured. In this case the distance between Railway/DFC boundary and fencing of house is 5.9m and edge of house is 7.55m. In this location concrete Boundary wall has been constructed by DFCCIL at Railway/DFC boundary to ensure safety. As new house has not been constructed with in 30m of railway boundary and the house exists before	
2		Due to continuous train movement and vibrations, my house and surrounding residential area have suffered severe structural damage, making it unsafe for habitation. Despite multiple complaints to DFCCIL officials and the local municipal corporation, no survey has been conducted, and no corrective action has been conducted, and no corrective action has been to intimidate us, violating our rights and the local by DFC officials Executive Engg/BL and confirmed that no vibrations observed during thence no such vibrations observed at this house due to train the confirmed that no co		
	3	My Demands: Immediate safety inspection of the area to a the risk to residents. Written clarification regarding the legali residential proximity to the tracks.	TO THE A PROPERTY OF THE PROPE	

Y. 200 16L 09/04/2025

	residential area due to DFCCIL's project and train	not permitted on Safety ground. As DFC has laid track on DFC/Railway land, no compensation is allowed.  DFC Officials i.e Executive/Engg/BL and land land land land land land land	
4	Strict action against harassment faced by residents when raising concerns.	Jr.Executive/Engg /BL has visited the house of Shri Manish V Patel and talked to him regarding his complain. No harassment has been done to the resident and inhabitant of the house.	
5	If this issue is not addressed within 30 days, I will escalate it to the Railway Ministry, NHRC, and the High Court for legal intervention. I urge you to take urgent action to prevent further damage and ensure our safety.		

A sketch and photos showing exact distance between DFC track and house is enclosed here with at Annexure A for ready reference.Dy.PM/Engg/BL is requested to kindly take further necessary action forward the case.

Executive Engg/BI

DY.PM/ENER/BL. The detailed remarks of the generales of Shri Manish V Rathod is tetalated by above after.

Shri Manish V Rathod is tetalated by above after.


Carrying Inspection of & house by Executive Engr/BL on 07/07/2025. Dy.CPM/Engs/BL is requested of 100 Kindly to be furthernecessary action


DJP4/E198/BL

DJCPM/E/10/8 - 07/4/25

APIO/MUM-N

Sub: Inspection of house of Shri Manish V patel Ref: MORLY/E/2025/0007493 dated 07.03 2025





Height of boulding = 6.3 m Height of boulding from topaf DFC Upline = 5 m Height from ground level = 63m = H Claurance required = 1/2 = 3.15 m (learance from Rahay boundary = 7.55 m =

