



Dedicated Freight Corridor Corporation of India Ltd.

(A Government of India Enterprises)

5<sup>th</sup> Floor, Pragati Maidan, Metro Station Building Complex, New Delhi- 110001  
Corporate Identity Number U60232DL2006GOI155068 Web:  
[www.dfccil.gov.in](http://www.dfccil.gov.in)

No. 2018/HQ/Admin/RTI-106

New Delhi: 09.04.2018

Shri Rajendra Kumar Jain  
24, North Vijay Nagar Colony  
Agra-282004  
Mobile-8449300092

Subject: Providing information w.r.t. Original Application received under the RTI Act.2005.

Reference: Original Application dated 11.04.17 received on 22.02.18 from Sh. Rajendra Kumar Jain.

Information i. r. o. your above RTI application as received is attached as Annex "A".

Hope the above information is complete and satisfactory. If not, then you can appeal within 30 days of receipt of the letter to the 1st Appellate Authority whose name and address is as under;

Shri Satish Kothari, GGM/ Administration DFCCIL,  
5th Floor, Pragati Maidan Metro Station Building, New Delhi-110001.

(S.K.PANDA)

Dy. G.M/Admn.(PIO)

E-mail: [skpanda@dfcc.co.in](mailto:skpanda@dfcc.co.in)

9717636811

Copy to

CPM/Tundla 1- for Information & Record only



डेडीकेटेड फ्रेट कोरीडोर कारपोरेशन ऑफ इण्डिया लिमिटेड

(रेल मंत्रालय का उपक्रम)

DEDICATED FREIGHT CORRIDOR CORPORATION OF INDIA LIMITED

(AN UNDERTAKING OF MINISTRY OF RAILWAYS)

डेडीकेटेड फ्रेट कोरीडोर

TDL/EN/RTI/212/(A)  
DGM/PIO  
DFCCIL  
New Delhi,

Date- 07.04.2018

Sub: - Application of Sh. Rajendra Kumar Jain R/o Agra, regarding of information under RTI Act. 2005.

- Ref:- I HQ Letter No. 2017/HQ/ADMIN/RTI-106 dated 27.02.2018 received on 09.03.2018 & 2017/HQ/ADMIN/RTI-106 dated 26.03.2018 received on 02.04.2018.
- II This office Letter no TDL/EN/RTI/212(A) dated 15.03.2018.
- III PMC Letter no. SAI/TYPSA/PMC/Y18-M03/1719 dated 04.04.2018 received on dated 06.04.2018.

- I. Vide reference I. RTI of Sh. Rajendra Kumar Jain R/o Agra, HQ Letter No. 2017/HQ/ADMIN/RTI-106 dated 27.02.2018 received on 09.03.2018 & 2017/HQ/ADMIN/RTI-106 dated 26.03.2018 received on 02.04.2018
- II. Vide reference III, item wise reply submitted by PMC is hereby attached for your kind reference and necessary action please.

Enclosed: - 04 Pages

(Subhash Chandra)

Dy. Chief Project Manager/Ele./TDL

Sp. M - 370/2018  
RECEIVED  
Date 9/4  
Sign. [Signature]  
DGM/PIO Office

link to examine for mpmg.  
for only

Office Of Chief Project Manager:- 3/20, 3rd Floor, KPS Tower, Mayur Complex, Nagla Padli,  
Near Tulsi Cinema, NH-02, Agra - 282002

Telefax: 0562-2885577 E mail: abkhare@dfcc.co.in, Mob. 7060803000

Website [www.dfccil.gov.in](http://www.dfccil.gov.in)

Ref. No. SAI-TYPSA/PMC/DFCCIL/Y18-M03/1719

05-04-2018

**The Chief Project Manager,**

Mr. Atul. B. Khare,

Dedicated Freight Corridor Corporation of India Ltd,

A Government of India (Ministry of Railways) Enterprise,

3/20, 3<sup>rd</sup> Floor, KPS Tower, Mayur Complex; Nagla Padi

Near Tulsī Cinema, NH-02, Agra -282002

Email: [abkhare@dfcc.co.in](mailto:abkhare@dfcc.co.in)

**Sub - Design and Construction of Civil, Structures, and Track Works for Double Line Railway involving formation in Embankments/Cuttings, Ballast on Formation, Track Works, Structures, Buildings, including Testing and Commissioning on Design – Build Lump Sum basis for Bhaupur - Khurja Section of Eastern Dedicated Freight Corridor – RTI application of Shri Rajender Kumar Jain R/O Agra, UP Under RTI Act- 2005 – Reg.**

**Ref:**

1. Notification of Award (LOA) vide letter no. HQ/EN/DB/Bhaupur-Khurja dated: 24.01.2013.
2. Contract Agreement HQ/EN/DB/Bhaupur-Khurja/LOT-103 dated 08.03.2013.
3. HQ letter 2018/HQ/Admin/RTI -106 dated 27.02.2018 received on 13.03.2018
4. DFC Letter no TDL/EN/RTI/212 (A) dated 15.03.2017 ,17.03.2018

Dear Sir,

We are herewith submitting point wise reply to quarries in regard to RTI application of shree R.k.jain as requested in your letter (4) cited above.

- 1) List of structures in which cracks have been developed.

No crack was observed in any of the major/minor structures in LOT-101.

A	B	C	D	
<b>LOT-102: STATUS OF MAJOR STRUCTURES CRACKS</b>				
<b>S No</b>	<b>Structure No</b>	<b>Location</b>	Cracks repaired satisfactory	
1	TD-MJRUB	10+263		
3	TD-RFO	9+841		
4	TD-IOCL	10+031		
<b>LOT-102: STATUS OF MINOR STRUCTURES CRACKS</b>				
<b>S No</b>	<b>Str No</b>	<b>Location</b>		
1	FDBR-04	8+655		
2	FDBR-06	8+763		
3	FDBR-07	9+067		
4	FDBR-09	9+803		
5	FDBR-10	9+908		

6	FDBR-11	10+110		
7	FDBR-12	10+324		
8	TDBR-14	8+588		
9	TDBR-15	8+724		
10	TDBR-10	4+680		
11	TDBR-11	5+084		
12	TDBR-12	5+186		
13	TDBR-07	4+390		
14	TDRUB-4A	4+314		
15	TDRUB-4B	5+643		
16	TDRUB-5A	6+653		
17	TDRUB-06	6+829		
A	B	C		D
S No	Structure No	Location		
18	TDRUB-07	8+120		Cracks repaired satisfactory
19	TDRUB-08	8+903		
20	TDRC-01	1+735		
21	TDRC-08	9+569		
22	TDBR-17	10+573		
23	TDBR-18	11+487		
24	TDBR-19	12+731		
25	TDBR-08	4+524		
26	TDBR-09	4+596		
27	BDRUB-01	0+987		
28	BDRUB-02	1+387		
29	BDBR-02	2+267		
30	BDRUB-04	2+854		

**Status of Repairing of Crackes in Major Structures at LOT 103**

**Few Important submissions from JV for Repairing of Crackes in Major Structures at LOT 103**

1.	TATA-ALDESA/EDFCCIL/ALJN/ENG/LOT103/2016-2017/2039 Dated 07.10.2016	Submission report on Investigation of Vertical cracks and remedial measures in Major Bridges
2.	SAI-TYPSA/PMC/TATA/103/Y17-M01/0637 dated 11.01.2017	Suggestions from PMC reg remedial measures


3.	SAI-TYPSA/PMC/Y17-M01/3079 31.01.2017	dated	Suggestions from PMC for inspection of CRR1
4.	TATA- ALDESA/EDFCCIL/ALJN/ENG/LOT103/2016 -2017/2217 Dated 07.10.2016		JV submission of Method Statement for cutting and re-baring work (HILTI)
5.	SAI-TYPSA/PMC/TATA/103/Y17-M02/0651 dated 20.02.2017		Suggestions from PMC Proposals should be shared with M/s STUP
6.	STUP - Consultant Pvt Ltd Letter dated E/8060/SKP: vsj/2491 Dated 16.11.2017		Approval of STUP
7.	TATA- ALDESA/EDFCCIL/ALJN/ENG/LOT103/2017 -2018/2573 Dated 20.09.2017		JV submission of Method Statement for Repairing
8.	SAI-TYPSA/PMC/Y17-M11/3581 22.11.2017	dated	Approval from PMC

S No	MJ. STR.	References of Observation Raised	CRACKS DESCRIPTION	Rectify/ Repairing References	Date
1	RUB ALG MJ2	SAI- TYPSA/PMC/LOT103/Y 16-M09/552 Dated 10.09.2016	A2 LHS - Three locations between the pedestal	RFI No MJBR/5363 RFI No MJBR/4401	30.12.2017 18.01.2017
2	RUB ALG - 1	SAI- TYPSA/PMC/LOT103/Y 16-M09/552 Dated 10.09.2016	A1 LHS - Median side pedestal (ONE Location) A2 LHS - Median side pedestal (ONE Location)	RFI No MJBR/4766	21.07.2017
3	Br.10 5A	SAI- TYPSA/PMC/LOT103/Y 16-M09/552 Dated 10.09.2016	A1 RHS - Two location in side A1 - On top surface three cracks A2 RHS - Two location in side	RFI No MJBR/4429 RFI No MJBR/4602 RFI No MJBR/4780	25.01.2017 16.05.2017 25.07.2017
4	HTMJ 2 & 3	Site Visit	A1 & A2 top surface	RFI No MJBR/4787	29.07.2017
5	HTMJ 1	Site Visit	A1 & A2 top surface both side	RFI No MJBR/4788	29.07.2017

- 2) Copy of order /letter vide which Sri Anshuman Sharma, Director, DFCCIL has issued instructions to dismantle such unsafe structures to the Contractor - No such instruction has issued from Director, however, only Repairs of cracks have been carried out based on instructions of CRR1 Delhi and Civil Aid Bangalore after site investigation.

Hope above information's meets your satisfaction.

Sincerely,  
For SAI-TYPSA (JV)



**Blaine Peterson**

**Team Leader**

[bpeterson@systra.com](mailto:bpeterson@systra.com); +91 7895991801

**Copy to:**

1. Mr. Manjul Mathur / GGM / Multi Agency / EC /DFCCIL/ New Delhi.