

Reply

Sub.: Information under RTI Act sought by Applicant-Sh. Subhash Chand vide his Application (RTI reference No. DFCCIL/R/E/21/00920 dated 26/10/21

Ref.: DGM/Admin(PIO) note dated 26/10/2021 (RTI 1161)

In reference to above, reply to the information pertaining to DFCCIL sought by the Applicant is as under:

Question	Reply
If any CRO(CATTLE RUN OVER) occurred in Station yard than who or which Department (Engineering Or Operating) responsible to clear track?	As per Annexure 3, point No. 13 of document DFCCIL/EN/TDL/Track Maintenance/2019 available in DFCCIL, it is the duty of Engineering Department to Clear the track after happening of CRO (Cattle Run Over)

This has the approval of GM/Traffic & Safety.

JGM/Admin/PIO


DGM/Traffic
12/11/2021